EPA Region 5 Records Ctr.



7/29/00

	EPA WORK ASS	SIGNMENT FORM (WAF) FOR R	AC	
1. WORK ASSIGNMEN	T (WA) INFORMATION				
Project Name: North Bron	son Industrial Area Bronson,	MI Contractor: Roy F. West	ton, Inc.	WAN	No.: <u>031-ROBE-051C</u>
Activity: Remedial Design	Oversight EPA Co	ontract No. <u>68-W7-0026</u>	Revi	sion No.: <u>003</u>	
Date: September 5, 2000		Ontractor Control No. Modi (Contracting Officer U		ification No.: lse Only)	
2. DESCRIPTION OF A					
New WA (need WP for the WA) Attach SOW including schedule Designate WAM		— Partial WP Approval — WP Disapproval — Final WP Approval — Amendment to Final WP Approval Approve change in LOE, scope, or budget Approve additional tasks	Technical Direction		Incremental Funding . Fund approved WP WA Closeout Notification . Notify contractor to initiate WA closeout task . Revise EL after final invoiceOther
B. BUDGET INFORMA	TION			T	
Completion WAX_ Term WA		Approved Work Plan Budget		Expenditure Limits Not to Be Exceeded	
Total Funding Received (\$) Previous Total 0 This Action 0 New Total 0		LOE (\$)* Term WAs Only		LOE Term WAs	25,000
Funding Category: Site Characterization Activity Code: BE S/SID: 051C		* Includes fees		0	0
4. WA COMPLETION I	DATE Current: Apr	ril 30, 2,001	Revised:		
5. EPA COMMENTS: The contractor shall 5, 2000.	l prepare a work plan i	in accordance with the atta	ached Statement	of Work R	evisionn dated September
Contractor Signatures:		EPA Signatures: R Clark Morino 9/5/0			
Site Manager/Firm		Date Date Phone Number (312) 886-7251			
	pproved With Not Approv	Par	t Officer, Pat Vogtuna Ollo Contracting Officer,	D _b	1/Date / 9/11/00

СО Сору ____

PO Copy ____

WAM Copy ____